

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name	2. Date Prepared	3. Time Prepared
		Kalamazoo River/Enbridge Oil Spill	07/23/2012	1800
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 1200, 07/19/12 – 1200, 07/26/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Aerial Field Observer		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<b>Operational Observation:</b> <ul style="list-style-type: none"> <li>MP5.63 Railroad Trestles observed sheen and tar globs.</li> <li>MP5.63 Railroad Trestles observed sheen sweep boat/boom maintenance boat operating.</li> <li>Ceresco Dam Control Point observed sheen and debris collecting within boom.</li> <li>Ceresco Dam Control Point boom maintenance crew observed preparing to remove debris from boom.</li> <li>Ceresco Dam Control Point boom observed sheen collecting.</li> <li>MP5.7 RDB observed large patches of sheen.</li> <li>MP5.5 center channel observed sheen and tar globs.</li> </ul>			
10:00	<ul style="list-style-type: none"> <li>Removed the boat and mobilized to D2 boat launch.</li> <li>Stopped by C5 boat launch, MP14.75 observed the sheen sweep boat operating.</li> <li>Stopped on Burnham Bridge, MP15.5 South Mill Pond no sheen observed.</li> </ul>			
10:30	<ul style="list-style-type: none"> <li>Launch Boat</li> <li>MP20.4 Observed quantification coring.</li> <li>MP20.4 observed sheen when boat agitated the sediment.</li> </ul>			
11:30	<ul style="list-style-type: none"> <li>Removed boat from river and mobilized to Shady Bend Campground.</li> <li>MP26.25 RDB tiny ribbons of sheen observed.</li> <li>MP26.0 RDB no sheen observed.</li> <li>MP24.75 LDB no sheen observed</li> <li>MP23.10 observed sheen, operations was notified.</li> <li>MP20.0 LDB observed quantification coring team.</li> <li>MP29.25 observed the navigational stakes reinstalled.</li> <li>MP36.25 observed sheen.</li> <li>Morrow Lake Delta observed the poling crew</li> <li>Morrow Lake Delta observed sheen sweep boat operating along Boom C.</li> </ul>			

1700	<ul style="list-style-type: none"><li>• Morrow Lake, observed the sweep boat operating.</li><li>• Morrow Lake Delta agitation effects study</li><li>• MP34.5 LDB observed unknown structure deployed in the river.</li><li>• Removed Boat from river</li></ul> <p><b>Planning Activities:</b></p> <ul style="list-style-type: none"><li>• Completed 214</li><li>• Prepared and distributed Daily Situation Unit Photolog.</li><li>• Continued preparation of weekly Situation Report "SitRep"</li><li>• Continued updating Organizational Staffing Gannt Chart.</li></ul>
9. Prepared by (Name and Position) Matthew Haak, Situation Unit, USEPA-START	